

Información Técnica (TI) de Fábrica a Distribuidores

<u>MODEL and YEAR</u> EC 250 / 300 2018	<u>SUBJECT:</u> CDI: Wrong mapping	<u>FECHA</u> <u>EMISION:</u> March 9th, 2018	<u>TI Nº:</u> GGT – 04
---	--	--	----------------------------------

<u>Symptom:</u>	Too lean combustión mixture. This might provoke engine broken (Piston-cylinder) The CDI (EE51100CT-CRB-1) have a wrong mapping installed.
<u>Countermeasure:</u> <u>Repair Procedure:</u> <u>Affected lot:</u>	According the ATTACHED LIST OF AFFECTED VIN's. is need to reprograma ll of them urgently. You have been received a CABLE the is need need for the upgrade.  Follow the ATTACHED EXCEL FILE for the upgrade procedure.
<u>Picture:</u>	EE51100CT-CRB-1  ➔ EE51100CT-CSK-1 

<u>Countermeasure parts:</u>	Please submit the warranty application to DEIWEB with the part number and its VIN. EE5100CT-CSK-1		
<u>Labour time:</u>	10 minutes		
<u>Labour price:</u>	35€ / Hour		
Warranty Application: Deiweb			

Please do not hesitate to contact:

Mr Aleix Julia

ajulia@gasgas.com

+34 662132011 (cell)

Warranty administration and Service Customer relation

(New) Mr. Daniel A. Andrade **dandrade@torrot.com**

+34 972406115 ext: 209

Technical assistance

Mr. Dani Ortiz

dortiz@torrot.com

+34 972406115 ext: 314