


REF: 20170929

Technical buletin N° 3 : Clutch lock washer EC 250/300 2018

Dear Distributor:

We inform you that have been applied a modification in the clutch lock WASHER fitted in the EC 250/300 2018.

The new washer **ME21120GG-CLJ-1** has the two slimmer nails to be better fitment in the new clutch basket of the 2018 YM.



This modification has been implemented to the following V.I.N.

EC 250 : **VTR4E2500J0970197**

EC 300 : **VTR4E3000J0970954**

Therefore, is necessary to replace with the new clutch lock WASHER during any clutch maintenance-repair.

Verify if the unit is within the affected lot.

Furthermore, the two par numbers will remain active.

ME25632022


For models until 2018 YM

ME21120GG-CLJ-1

For 2018 YM

Previous **ME25632022**
For models until 2018 YM
EC 250/300 2017

New **ME21120GG-CLJ-1**
For 2018 YM EC 250/300 2018



Service Dpt

GAS GAS MOTOS S.A.

E.mail csanchez@gasgasmotos.es